

## Humidity & Temperature Meters



Large LCD display



EMC  
EN: 50081-1, 50082-1  
EN: 60825-1

616CT is Humidity meter plus Air and IR temperature thermometer.

615 is Humidity meter plus Air and K-type thermocouple thermometer.

- Large, easy-to-read backlit LCD with dual display
- Max & Hold function
- Auto Power Off

### Features

	615	616CT
Dual LCD display	*	*
IR Temperature with Laser pointer		*
K-type temperature	*	
Air temperature	*	*
°C/°F switchable	*	*
Max and Hold function	*	*
Auto Power Off	*	*
Backlit LCD display	*	*
Low battery indication	*	*

Non-contact Temperature Measurement



### Specifications

	615 (K-type Temp.)	616CT (Infrared Temp.)
Temperature Range	-20°C~1000°C/ -4°F~1832°F	-50°C~500°C/ -58°F~932°F
Resolution	0.1° up to 200°, 1° over 200°	0.1° up to 200°, 1° over 200°
Basic Accuracy	±3.0%	±2.0%±2°C/4°F
Humidity Range	0%RH~100%RH	0%RH~100%RH
Resolution	0.1%RH	0.1%RH
Accuracy	±3.5%RH	±3.5%RH
Distance to Spot size		8:1
Emissivity		Fixed at 0.95

Size(HxWxD): 150mm x 72mm x 35mm

Weight: 210g

Accessories :

K-type temperature probe (615), Humidity Probe (615, 615CT) and 9V battery.